

## **Appendix E**

### **Photo Log**



**Photo 1: Looking toward the downstream side of the Plumtree and Route 40 crossing. Photo taken January 18, 2017.**



**Photo 2: Looking toward the upstream side of the Plumtree and Rt 40 crossing. Photo taken January 18, 2017.**



**Photo 3: Looking toward the upstream side of the Plumtree Branch and Longview Drive crossing. Photo taken January 18, 2017.**



**Photo 4: Looking downstream at erosion along Plumtree Branch from Longview Drive. Photo taken January 18, 2017.**



**Photo 5: Looking at the downstream side of the Plumtree Branch at Brookmede Road crossing. Photo taken January 18, 2017.**



**Photo 6: Looking at the upstream side of the Plumtree Branch at Brookmede Road crossing. Photo taken January 18, 2017.**



**Photo 7: Looking at the downstream side of the Plumtree Branch crossing at Hearthstone Road. Photo taken January 18, 2017.**



**Photo 8: Looking at the upstream side of the Plumtree Branch crossing at Hearthstone Road. Photo taken January 18, 2017.**



**Photo 9: Looking at the downstream side of the Little Plumtree Branch crossing at Michaels Way. Photo taken January 18, 2017.**



**Photo 10: Looking at the downstream side of the Little Plumtree Branch crossing at the private driveway entrance to Resurrection St. Paul School. Photo taken January 18, 2017.**



**Photo 11: Looking at the downstream side of the Little Plumtree Branch crossing at N. Chatham Road. Photo taken January 18, 2017.**



**Photo 12: Looking at the downstream side of the Little Plumtree Branch crossing of Route 40. Photo taken January 18, 2017.**